

ROYAL ZEPHYR RAILROAD RESTAURANT



Owner/Developer:

Gulfstream Development - Robert Harris

INDIVIDUAL EXPERIENCE FOR:

Kenneth R. Christenbury, P.E. 2004-2005

The Royal Zephyr Railroad Restaurant is located on a site with virtually no stormwater outfall. Mr. Christenbury assisted in negotiations with adjoining property owners in the acquisition of an easement. Due to limited available space, the outfall was only accessible through the design and construction of a stormwater pump station. The site has insufficient area for conventional stormwater management basins, so concrete basins were constructed for stormwater management and to contribute to the aesthetic appeal of the project by emulating a railroad bridge.

